

Libby, Montana
 Railyard Loading Station
 Asbestos Levels in Soil (by PLM)

Field Samples

- ND
- <1%
- 1%
- 2%
- 3%
- 4%

Depth Sample Results

- ND
- <1 %
- 1 %
- 2 %

Duplicates

- ND
- <1 %
- 1 %
- 2 %
- 3 %

PLM Results Not Depicted

B00067 1% Tremolite-Actinolite
 B00075 <1% Tremolite-Actinolite



Contract No.: N00174-99-D-003
 Delivery Order No.: 0003
 Purchase Order No.: 0003 2859
 EPA ID No.: DW1765000-01-0



1225792 - R8 SDMS

LIBBY #2